

For the part number 10.0610.017 please use the cable stripping K3.



M 36

Montageanleitung
Assembly Instruction

IMS CONNECTOR SYSTEMS

HF-Steckverbinder
RF Connectors

Gehäuse
Housing



löten
solder

